

**** Aqua Lung Consumer Notice ****

Recall – SureLock II Weight Pocket Handles

Aqua Lung is conducting a voluntary recall of SureLock II weight pocket handles.

Sure Lock II is the mechanical weight release system found on most Aqua Lung buoyancy compensators (BCs) beginning in 2009. Aqua Lung is concerned about the rubber handle pulling off of the plastic Sure Lock II weight pocket assembly. If this were to occur during a dive, the weight pocket would be left engaged inside the BC. There are no known occurrences of this happening underwater, and there have not been any reported injuries, but Aqua Lung believes that a recall is the safe and prudent thing to do.

Aqua Lung has made a revision to the handle assembly that strengthens it. A revised handle is easily recognized by a thickened band of rubber at the base of the handle.



New revision i
by a band of t
material on th
underside of t
handle

For more information, please visit us at www.1-800-4-A-FAIRWAY.com or call 1-800-4-A-FAIRWAY. © 2014 Callaway Golf Company. All rights reserved.